National Transportation Safety Board
FACTUAL REPORT
Occurrence Date: 08/18/2000 Most Critical Injury: Fatal
Occurrence Type: Accident Investigated By: NTSB

Location/Time
Nearest City/Place State Zip Code Local Time Time Zone

33950

Distance From Landing Facility:

EDT

Airport Proximity: Off Airport/Airstrip
Aircraft Information Summary

PUNTA GORDA

Aircraft Manufacturer Model/Series Type of Aircraft

Burgess AIR COMMAND /AIR COMMAN Unknown

1910

Revenue Sightseeing Flight: No Air Medical Transport Flight: No

FL

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On August 18, 2000, at about 1910 eastern daylight time, a Burgess Air Command 432, N6292, registered to a private owner, operating as a 14 CFR Part 91 personal flight, crashed while maneuvering in the vicinity of Punta Gorda, Florida. Visual meteorological conditions prevailed and no flight plan was filed. The rotorcraft was destroyed. The recreational pilot was fatally injured. The flight originated from Punta Gorda at an undetermined time.

Witnesses stated they observed the aircraft flying overhead at a low altitude, and it was observed doing some abrupt maneuvers. A witness stated, "It looked like he was trying to do a trick." The engine was under power the entire time. Additional witnesses stated they observed the nose pitch up about 90 degrees, the aircraft banked 90 degrees to the left, went inverted, and fell out of the sky. Another witness who was located at her home with her daughter stated they saw the aircraft flying overhead at a low altitude. "Next thing I saw him do like a donut (go upside down) then it went straight into my trees and hit the power." (For additional information see Charlotte County Sheriff's Office/Punta Gorda, Florida, Incident/Offense Report, an attachment to this report.)

The original builder of the gyroplane plane stated he sold the aircraft to an individual in Fort Myers, Florida. The new owner sold the aircraft to the deceased pilot. The builder of the aircraft stated, "On Wednesday, August 17, while driving, I observed the gyro flying over a residential area at low altitude and doing radical maneuvers. The gyro was making steep turns and diving at the ground then doing steep pull-ups. I had planned on calling Jim when I got back in town on Saturday to discuss his flying with him regarding this incident. His crashed happened on Friday before I returned. Upon discussing this accident with other members of our local gyroplane club, I was made aware of several incidents of unsafe flying that Jim had been witnessed doing. He had been warned several times about flying too low and maneuvering too close to the ground."

Attempts to locate the pilot logbook and aircraft logbooks by the FAA were uneventful. Review of airman records on file with the FAA in Oklahoma City, Oklahoma, revealed the pilot was issued a recreational pilot certificate on June 20, 1993, with rating for airplane single engine land. He held a third class medical certificate with no restrictions issued on June 7, 2000 with no restrictions. No determination of total airman flight time could be made. According to the builder of the gyroplane, the deceased pilot's brother indicated the deceased pilot was an accomplished aerobatic pilot.

The wreckage of N6292 was located in the vicinity of 29290 Leah Road Punta Gorda, Florida. Examination of the wreckage revealed the aircraft had collided with power lines and a fence during the crash sequence. There was no evidence of a precrash mechanical failure or malfunction of the airframe, flight controls, or engine assembly. (For additional information see FAA Inspector statement, an attachment to this report.)

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: MIA00LA241

Occurrence Date: 08/18/2000

Occurrence Type: Accident

Narrative (Continued)

Dr. Sajid Qaiser, Associate Medical Examiner, District 22, Port Charlotte, Florida conducted postmortem examination of the pilot, on August 21, 2000. The cause of death was multiple injuries. The Forensic Toxicology Research Section, Federal Aviation Administration, and Oklahoma City, Oklahoma performed postmortem toxicology of specimens from the pilot. These studies were negative for carbon monoxide and cyanide. Ethanol 20 (mg/dl, mg/hg) was detected in the blood, 35 (mg/dl, mg/hg) was detected in the brain, 58 (mg/dl, mg/hg) in the urine. Acetaldehyde (18 mg/dl, mg/hg) was detected in the urine, phenylpropanolamine, ephedrine, and pseudoephedrine was detected in the urine.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: MIA00LA241

Occurrence Date: 08/18/2000

AVIATION			nce Type:	Accident							
Landing Facility/Approach Inf	formation										
Airport Name	port ID:	Airport Elevation	Run	Runway Used Run			h Ru	unway Width			
				Ft. MSL	0						
Runway Surface Type:							<u> </u>				
Runway Surface Condition:											
·											
Approach/Arrival Flown: NONE											
VFR Approach/Landing: None											
Aircraft Information											
Aircraft Manufacturer			Model/						Number		
Burgess			AIR C	COMMAND /A	AIR CO	MMAN		6292			
Airworthiness Certificate(s): Exper	imental (Special)										
Landing Gear Type: Tailwheel											
Amateur Built Acft? Yes Number of Seats:			Certified	d Max Gross Wt.	LBS Numbe			r of Engir	nes: 1		
Engine Type: Er Unknown			Engine Manufacturer: Model/Series:						Rated Power:		
- Aircraft Inspection Information											
Type of Last Inspection		Da	Date of Last Inspection Time			nce Last Inspe	ection		Airframe	Total Time	
Unknown							Hours			Hours	
- Emergency Locator Transmitter (B	ELT) Information							•			
ELT Installed?/Type No	LT Operated? ELT Aided in Locating Accident Site?										
Owner/Operator Information											
Registered Aircraft Owner			Street A	ddress 6292 MORG	NIAN	F					
JOSEPH H. BURGESS			City							Zip Code	
			0, , ,	FORT MYER	FL	33912					
Operator of Aircraft			Street A	aaress 24376 BUCC	ANEER	BLVD					
JAMES V. AURANDT			City							Zip Code	
	PUNTA GORDA FL							33955			
Operator Does Business As: Operator Designator Code:											
- Type of U.S. Certificate(s) Held: N											
Air Carrier Operating Certificate(s):											
Operating Certificate:	Operating Certificate: Operator Certificate:										
Regulation Flight Conducted Under	: Part 91: Genera	l Aviation	1								
Type of Flight Operation Conducted	: Personal										
		FACTUA	L REPO	RT - AVIATION						Page 2	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: MIA00LA241

Occurrence Date: 08/18/2000

	AVIATI	Occurren	Occurrence Type: Accident													
First Pilot	Information															
Name						City					Sta	ate	Date	of Birth	Age	
On File			On File				On	File	On F	File	32					
Sex: M Seat Occupied: Front Occupational Pilot? Business										Ce	rtifica	te Num	ber: O	n File		
Certificate(s):																
Airplane Rating(s): Single-engine Land																
Rotorcraft/Glider/LTA: None												Т				
Instrument	Rating(s): Non	e														
Instructor Rating(s): None																
Current Biennial Flight Review?																
Medical Ce	rt.: Class 3	Med	ical Cert. Stat	us: Valid Me	dicalno wa	aivers/	lim.		[Date of La	ast M	edical E	Exam:	06/2000		
																_
- Flight Tim	- Flight Time Matrix All A/C This Make and Model		Airplane Single Engine	Airplane Mult-Engine	Night Actu		Actual	Instrument al Simulated			Rotorcraft		Glider	Lighter Than Air		
Total Time																
Pilot In Cor	nmand(PIC)															
Instructor																
Instruction	Received															
Last 90 Day	ys															
Last 30 Da	ys															
Last 24 Ho	urs	<u> </u>														
Seatbelt Us	ed? Yes	Sh	oulder Harne	ss Used? No			Toxico	Toxicology Performed? Yes Second Pilot? No						0		
Flight Pla	n/Itinerary											•				
Type of Flig	ght Plan Filed: No	one														
Departure l	Point				•		State	State Airpor			oort Identifier			Departure Time		
Same as	Accident/Incide	ent Location	n					PGD			0000					
Destination								State Airport Identif			er					
Local Flight																
Type of Clearance: None																
Type of Airspace: Class G																
Weather Information																
Source of Wx Information:																
No record of briefing																
				FACTUAI	L REPORT	- AVI	ATION	1							Page 3	

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: MIA00LA241

Occurrence Date: 08/18/2000

AVIATION				Occurrence Type: Accident									
Weather Information													
WOF ID	ID Observation Time Time Zone WOF Elevation			on	WOF Di	istance From	n Accid	ent Site Direction F			rom Accident	Site	
PGD	1853	EDT		27 Ft.	MSL				0 NM			0 De	eg. Mag.
Sky/Lowes	st Cloud Condition: Clear	·					0 Ft. AG	SL	Condition of Light: Day				
Lowest Cei	iling: None			0 Ft.	AGL	Visibi	Visibility: 10			Alti	meter: 30.00 "H		
Temperatu	ıre: 36 °C [Dew Point:		19 °C	Weath	ner Condi	tions at Acci	ident S	ite: Visual (Conc	litions		
Wind Direc	etion:	Wind Spe	ed:			Wind	d Gusts:						
Visibility (R	RVR): 0 Ft.	Visibility	(RVV)	0	SM								
Precip and	l/or Obscuration:												
Accident	Information												
Aircraft Dar	mage: Destroyed		Aiı	Aircraft Fire: None			Aircraft Exp	losio	n None				
- Injury Sur	mmary Matrix	Fatal	Serious	Mino	r	None	TOTAL						
First Pil	lot	1					1]					
Second	d Pilot												
Student	t Pilot							1					
Flight Ir	nstructor							1					
Check F	Pilot							1					
Flight E	ngineer]					
Cabin A	Attendants]					
Other C	Crew							1					
Passen	igers			†									
- TOTAL A	ABOARD -	1					1	1					
Other G	Ground	0	(0	0		0	1					
- GRAND) TOTAL -	1		0	0		1						

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: MIA00LA241

Occurrence Date: 08/18/2000

Occurrence Type: Accident

Δc	m	ınıc	trativa	Into	rmation
\neg	4111	เบเจ	uauve	HILL	ทากสแบบ

Investigator-In-Charge (IIC)

CARROL A. SMITH

Additional Persons Participating in This Accident/Incident Investigation:

PAUL E KAHLER TAMPA, FL